



Appendix B


Photographs from Institutional Controls Assessment and Operation and Maintenance Inspection



TRA-03 site, 4-23-03
PD030242-03.jpg




TRA-03 ECA sign, 4-23-03
PD030242-02.jpg




TRA-04 site, 4-23-03
PD030242-07.jpg




TRA-04 showing jersey barriers, 4-23-03
PD030242-06.jpg


	<p>TRA-13 and Soil Contamination Area, 4-23-03 PD030242-13.jpg</p> <p>TRA-19, 4-23-03 PD030242-15.jpg</p> <p>TRA-15, 4-23-03 PD030242-14.jpg</p> <p>TRA-08, 4-23-03 PD030242-11.jpg</p>
---	---



PCB site by TRA-619, 4-23-03
PD030242-20.jpg




TRA-34, 4-23-03
PD030242-16.jpg



PCB site by TRA-653, 4-23-03
PD030242-22.jpg



PCB site by TRA-653, 4-23-03
PD030242-21.jpg



TRA-Y, brass cap area, 4-23-03

PD030242-01.jpg



TRA-X, hot tree site, 4-23-03

PD030242-23.jpg



TRA-06 vegetation on 6-18-03

PD030242-10.jpg



TRA-06. 4-23-03

PD030242-09.jpg

	TRA-03 WWP on 6-18-03 PD030242-03.jpg	TRA-03 WWP, 6-18-03 PD030242-04.jpg	TRA-03 WWP, 6-18-03 PD030242-05.jpg
			
	TRA-13 and SCA on 6-18-03 PD030242-12.jpg	Close-up of new growth on TRA-13 on 6-18-03 PD030242-24.jpg	

